TOP STATE

BUT 25/88

25X1 25X1

123

TOPSECRET

PRITY

5033

- INFORMATION REGARDING 9041. 1.
- 2. DO YOU HAVE ANY DATA THAT INDICATES YAW PROBLEM PASS AG2?
- OUR PRELIMINARY INFORMATION INDICATES THAT THERE IS A SEVERE YAW PROBLEM DURING PASS A02. PLOTS OF PASS A02 SHOW A YAW CONDITION OF ABOUT 70 DEGREES. SAME SMALL IMAGE APPEARS ON FOUR FRAMES IN SEQUENCE ON FWD CAMERA; EXAMPLE, FRAMES 28, 29, 30, 31.
- QUICK CHECK OF FRAMING CAMERA INDICATES THAT YAW CONDITION DOES NOT CARRY ON INTO LATER PASSES, 39, 04 ETC.
- ALSO ROLL APPROXIMATELY 3 DEGREE 50' INDICATED ON FRAME 33, AØ2. SPEMS TO CORRECT OK LATER PASSES.
- SENDING THIS INFORMATION TO FOREWARN YOU AND TO GIVE YOU LEAD-TIME FOR PONDERING.

TOPSECRET

CFN: 5033 -X 9041 YAV AC2 AO2 AO2 A YAW 70 28 29 30 31 NOT CARRY 63 04 3 50° 33 A02 OK

BT

170

25X1

